




NTSB National Transportation Safety Board

Office of Aviation Safety



Emergency Response

Jennifer Rodi



Gate 48

Fed Ex Gate

Mutual Aid Gates

- No guidance for monitoring or maintenance during winter operations
- Iced gates delay response and aid

Number of Occupants

- Occupant information unavailable
- Estimated 2 or 3 occupants once on scene
- Search of cabin and debris field ensued
- Flight crew at hangar
- Prior knowledge could help prioritize duties

HAZMAT Information

- Search and query for HAZMAT manifest not initiated
- Federal Express provided HAZMAT manifest
- Prior knowledge could increase firefighter safety



NTSB